## MARYLAND HISTORICAL TRUST

MARYLAND HISTORICA	
DETERMINATION OF ELIGIE	BILITY FORM no
Property Name: Gwynnbrook Avenue Bridge	Inventory Number: BA 2693
Address: Gwynnbrook Avenue	Historic district: yes _X _ no
City: Owings Mills Zip Code: 21117-2810	County: Baltimore County
USGS Quadrangle(s): Reisterstown	
Property Owner: Baltimore County Dept of Public Works	Tax Account ID Number: N/A
Γax Map Parcel Number(s): 164 Tax Map N	Jumber:58
Project: Gwynnbrook Avenue Bridge Replacement Ag	gency: Baltimore County Dept of Public Works
Agency Prepared By: Whitman, Requardt and Associates, LLP	WINESCO TO THE STREET WAS ADOLD THE STREET WHO STONE
Preparer's Name: Sheryl Bernardo	Date Prepared: 4/5/2004
Documentation is presented in: Baltimore County Bridge Inspection Report	, 2001.
Preparer's Eligibility Recommendation: Eligibility recommen	dedX Eligibility not recommended
Criteria: A B C D Considerations: A	BCDEFG
Complete if the property is a contributing or non-contributing rese	ource to a NR district/property:
Name of the District/Property:	
Inventory Number: Eligible:	yes Listed: yes
Site visit by MHT Staff yesX no Name:	Date:
Description of Property and Justification: (Please attach map and photo)	
Bridge No. B0202 (BA 2693) carries Gwynnbrook Avenue over a tributary of bridge (structure) is located east of Owings Mills Boulevard in Reisterstown, roadway running in an east-west direction.  The structure is a concrete slab bridge supported on concrete abutments. The	Maryland. Gwynnbrook Avenue is a two-lane
MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended Eligibility not recommended	<u>X</u>
Criteria:ABCD Considerations:A	B _ C _ D _ E _ F _ G
MHT Comments: Bridge has lost integrity subseque	ueut to 2001 determination.
Thun Jan Quent	5/17/04
Reviewer, Office of Preservation Services	Date
Bluty	5/18/04
Reviewer, National Register Program	' Date

#### R-ELIGIBILITY REVIEW FORM

BA 2693

#### Gwynnbrook Avenue Bridge

Page 2

State Highway Administration (SHA). The bridge was subsequently widened (date unknown) after the initial construction date. The original parapets were removed during the widening project. The width of the bridge, curb to curb, is 20.0 feet. The out to out width is 22 feet. The bridge is skewed 45 degrees and has a length of 23.0 feet with a 22.0 foot span. The paved roadway width is 18 feet-8 inches. The wing walls are constructed of concrete and are flared approximately 10 degrees to the centerline of the bridge. The bridge is posted for a restricted load.

A Baltimore County Bridge Inspection Report was prepared in 2001 by Parsons Brikerhoff Quade and Douglas. The report identifies that the bridge is in poor condition due to the deteriorated condition of the deck and substructure. The report identifies several deficiencies regarding the bridge structure, thus warranting replacement of the bridge. These deficiencies are indicated in the concrete slab, reinforced abutment, wing walls and soffit, as reported in the Bridge Inspection Report:

Concrete Slab: The continuous asphalt-wearing surface is lightly worn. Moderate to severe honeycombing is exhibited on the north side of the widened portion of the bridge. Near the northern end of the original structure, there is a 10'-0" x 4'-0" hollow sounding area of concrete in the soffit. Within this hollow are there is a 6'-0" long x 5" wide x 3" deep spall with exposed reinforcing steel. Severe efflorescence and stalactites have formed at the joint between the original structure and the south widened portion. The ½ inch wide joint at the widened portion of the bridge has vertical displacement of 1-1/2 inches. There is a 3" diameter x 6" deep spall adjacent to the south parapet. The concrete in the southern widened bridge portion is hollow sounding and exhibits moderate cracking with severe efflorescence.

Reinforced Concrete Abutments: The concrete abutment stems both exhibit several full height hairline cracks and hollow sounding areas. The entire length of the west stem exhibits severe scaling and exposed aggregate. The south half of the west stem exhibits 1/16" hairline diagonal and vertical cracks with severe efflorescence within the widened portion of the stem. There is approximately 1-1/2" to 2" of separation between the original and widened portions of the east abutment at the north end of the abutment. The north half of the east stem exhibits moderate to severe scaling with exposed aggregate. The original concrete in the stem at the southwest and northeast ends respectively, of the abutments is hollow sounding. The south end of the west footing is heavily worn where the stream flows against it. A 1' x 1' area of the west footing is hollow sounding.

Wing walls and soffit: Spalling, scaling and hairline cracking are exhibited on the wing walls. The soffit exhibits numerous minor cracks and moderate to severe honeycombing.

The bridge is posted for limited load capacity of 13 tons, 17 tons, and 30 tons for the H15, MD Type 3 and the MD Type 3S2 vehicles, respectively.

The Area of Potential Effect (APE) for this bridge replacement project will follow the limits of disturbance (LOD) shown on the contract plans.

MARYLA	ND HISTO	DRICAL	TRUST	REVI	EW							
Eligibility 1	ecommen	ded		Eli	gibility not recomme	nded						
Criteria: MHT Com		В _	c _	D	Considerations:	A	В	c	D .	Е	F	G
***************************************	Review	er, Offic	e of Pres	servatio	on Services			Date			•	
) -	Revie	wer, Nat	tional Re	egister ]	Program	7		Date				

#### R-ELIGIBILITY REVIEW FORM

BA 2693

Page 3

#### Gwynnbrook Avenue Bridge


The bridge currently has a degree of compromise in regards to the amount of element destruction or replacement that has occurred over time. The total destruction or replacement of an element has major impact on that element's historic integrity, and depending on the element's importance on the historic integrity of the bridge as a whole. Bridge No. B0202 (BA 2693) has significant material deterioration of its superstructure and substructure, including its character defining elements and primary elements of importance (such as the removal of the original parapets during the undocumented bridge widening). Both the superstructure and substructure are in poor condition, having a major impact on the bridges historic integrity.

Normally a bridge replacement project that would result in the demolition of the entire structure would be considered an adverse effect. However, since the entire superstructure was expanded and substantial deterioration is present in our opinion this undertaking may not constitute an adverse effect, since the structure had already been compromised.

It is our recommendation that this bridge should be considered as not eligible for the National Register because of overall deterioration and the previous removal of character defining elements. Therefore, our Eligibility Recommendation status for the bridge is "Not Recommended".

MARYLA	ND HISTO	RICAL	TRUST	REVI	EW							
Eligibility 1	ecommen	ded		Eligibility not recommended								
Criteria: MHT Com	A ments:	В	C	D	Considerations:	A	В	C	D .	Е .	F	G
	Review	er, Offic	e of Pres	servatio	on Services	·	THE STATE OF THE S	Date				
-	Revie	wer, Nat	tional Re	egister l	Program	, manual		Date				_

# BA - 2693 Gwynnbrook Avenue Bridge



Reisterstown, MD 7.5 Minute Topographical USGS Quadrangle

BALTIMORE GUNTY



BA 2693 Gwynnbrook Avenive Bridge Saltimore County, MOST photography: Larry Murphy CUS ONE HOUR PHOTO: 4-6-04 Location of Negative MDSHPO North-Ederation of bridge photo 1 of 6



BA 2693 Gwynnbrook Avenue Bridge Baltimore County , mo photographer: Larry Murphy #--- 13UND4 CUS ONE HOUR PHOTO Location of Regutive: MDSHPO South elevation of bridges looking - portheast photo 20 f 6.0



BA 2693 Gwynn brook Avenue Bridge Baltimore Gonty, MP photographer: Larry Murphy Dato of Photo: 4-6-641 Location and Alegative: MOSAPO Spalls, Exposed Rebard : Cracking in Bridge Deck Soft it 2 photo -30f6



BA 2693 Gwynbrook Avenue Bridge Baltimore County, MD photographer: Larry murphy Date of Photo: 4-6-04 Location of Hegative: MO SHYD Heavy's Effloresænce and stalactites In Bridge Deck 30 ffit Photo 40+6



BA 2693 Gwynbrook Avenue Bridge Baltimore County, MD Photographer: Larry Murphy Station of negational and and son pounce Scaling In west Abutment Stern and cracked at widening interface. photo 5 of 6



BA 2693 Gwynn brook Avenue Bridge Baltimore County, MD photographer: Larry Murphy Photo Pate: 4-6-04 Location of Negative: MD SHPO Scaling in cast about ment stem and Crack at widening sourface. Photo 6 of 6

### **Maryland Historical Trust**

Maryland Inventory of Historic Properties number: BA-ZL973
Name: 130202/ Levynbrook ave over July of
The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the
Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001.
The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following
determination of eligibility.
MARINA AND ANGROPAGAY PROVINCE
MARYLAND HISTORICAL TRUST
Eligibility RecommendedX Eligibility Not Recommended
Criteria:ABCD Considerations:ABCD _EFG _None
Comments:
Reviewer, OPS: Anne E. Bruder Date: 3 April 2001
Reviewer, NR Program: Peter E. Kurtze Date: 3 April 2001

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT No. BA-2693

SHA Bridge No. B 0202 Bridge name Gwynnbrook Avenue over Tributary of Gwynns Falls
LOCATION: Street/Road name and number [facility carried] Gwynnbrook Avenue
City/town Owings Mills 0.1 mi E of Bonita Avenue Vicinity X
County Baltimore
This bridge projects over: Road Railway Water X Land
Ownership: State County X Municipal Other
HISTORIC STATUS:  Is bridge located within a designated historic district? Yes No _X_  National Register-listed district National Register-determined-eligible district  Locally-designated district Other  Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge Truss -Covered Trestle Timber-And-Concrete
Metal Truss Bridge
Movable Bridge: Swing: Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder:  Rolled Girder:  Rolled Girder Concrete Encased:  Plate Girder:  Plate Girder Concrete Encased:
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X :  Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Concrete Slab X Concrete Beam Rigid Frame Concrete Slab X Concrete Beam Slab Slab Slab Slab Slab Slab Slab Slab

BA-2693

DESCRIPTION:	<b>24</b>	211 (2017)	rishbasi
Setting: Urban Describe Setting:	Small town	Rural _	_X
Bridge B0202 carries Gw which flows in a southerly	ynnbrook Avenue in an east-wes y direction. The area is relatively rk adjacent to the bridge and tr	undeveloped wi	ith open fields to both side
width is 20.0 feet and the length of the structure is flared approximately 10 c integral to the deck. The	span concrete slab on concrete edeck out to out width is 22.0 is 23.0 feet. The skew is 45 degrees to the centerline of the be roadway supports two way traffort described the bridge as in factors.	feet. The span is rees. The wings or	is 22.0 feet and the overal walls are concrete and ar pets are solid concrete and
Discuss Major Alteration Baltimore County files d	ns: to not indicate that any major a	literations have	been undertaken.
HISTORY:			
WHEN was bridge built	(actual date or date range) 192	20_	
This date is: Actual X Source of date: Plaque _ Other (specify)	_ Design plans _ County br	ridge files/inspec	ction form X
WHY was the bridge but The need for a more eff following World War I.	It? icient transportation network a	nd increased loa	ad capacity in the decade
WHO was the designer? State Highway Administr	ration		
WHO was the builder? Unknown			
WHY was the bridge alto $N\!/A$	ered?		
	s part of an organized bridge-bene State to increase load capaci		
SURVEYOR/HISTORIA	N ANALYSIS:		
A - Events	ntional Register significance for B- Person rehitectural character		with:

Was the bridge constructed in response to significant events in Maryland or local history?

Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-04 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's road and bridge improvement programs mirrored economic cycles. The first road improvement program of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916 -1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war-related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920 to 1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund [with an equal sum from the counties] the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had become inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930s. Most improvements to local roads waited until the years after World War II.

With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer stated in 1906, "The general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do way with the further expense of the maintenance of expensive and dangerous wooden structures". Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

The creation of standard plans and a description of their use was first announced in the 1912-15 Reports of the State Roads Commission whereby bridges spanning up to 36 feet were to use standardized designs.

Published on a single sheet, the 1912 Standard Plans included those structures that were amenable to such an approach: slab spans, (deck) girder spans, box culverts, box bridges, abutments, and piers (State Roads Commission 1912). Slab spans, with lengths of 6 to 16 feet in two foot increments, featured a solid parapet that was integrated into the slab, with a roadway of 22 feet.

In the Report for the years 1916-1919, a revision of the standard plans was noted:

During the four years covered by this report, it has been found necessary to revise our standard plans for culverts and bridges, to take care of the increased tonnage which they have been forced to carry. Army cantonments...increased their operations several hundred per cent, and the brunt of the enormous truck traffic resulting therefrom, was borne by the

BA-2693

State Roads of Maryland. In addition to these war activities, freight motor lines from Baltimore to Washington, Philadelphia, New York, and various points throughout Maryland, and the weight of many of these trucks when loaded, was in excess of the loads for which our early bridges were designed (State Roads Commission 1920:56).

Published on separate sheets, the new standard plans (State Roads Commission 1919) for slab bridges reveal that the major changes was an increase in roadway width from 22 feet to 24 feet and a redesign of the reinforcement. The slab spans continued to feature solid parapets integrated into the span. The range of span lengths remained 6 to 16 feet, but the next year (1920) witnessed the issue of a supplemental plan for a 20 foot long slab span (State Roads Commission 1920).

Based upon documentary evidence, Baltimore County and City were the early pioneers in concrete bridge building in Maryland. The first reinforced concrete bridge documented in Maryland was the bridge at Sherwood Station, built in 1903 by Baltimore County.

Evidence from historic maps suggests that almost all of the extant concrete slab bridges built before 1940 in Baltimore County replaced earlier bridges. With the exception of two bridges, all of these structures lie on roads whose alignments have changed little since the middle of the nineteenth century. The two exceptions are both located on Shelbourne Avenue in Arbutus. Shelbourne Avenue does not appear on the 1850 map of Baltimore County but does appear on the 1915 map. Both concrete slabs bridges on Shelbourne Avenue, however, were built after 1915. The evidence therefore suggests that these two bridges were also built to replace previous structures.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence to suggest that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation?

Would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

The bridge is an undistinguished example of a concrete slab bridge.

Does the bridge retain integrity of important elements described in Context Addendum? The character defining elements appear to be intact.


Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer? The bridge is not a significant example of the work a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made? No additional study will be needed before an evaluation of the significance of this bridge is made.

BIBLIOGRAPHY:			
County inspection/bridge files	X	SHA inspection/bridge files	
Other (list):			

### **SURVEYOR:**

Date bridge recorded	08/15/95	
Name of surveyor	Colin Farr	
Organization/Address	P.A.C. Spero & Company	, Suite 412, 40 West Chesapeake Ave., Baltimore,
MD 21204		
Phone number (410) 2	296-1635	FAX number (410) 296-1670





Name	OF C	GWYNNS F	R A TRIBUTARY ALLS
County/State	BALT	IMURE COM	NTY /MD
Name of Pho	otographe	DAVE DIE	HL
Date 19	<u> </u>		
Location of	Negative	SHA	
Description		APPROACH	LOOKING
	EAST	- 1117 TOSE	11 Julia 20 July



Inventory # 100262 - G WY Name DF	NN BROOK	AVE OVER	a tributary
Name OF	DON TO	MURE COUN	TYLINA
County/State	JOHL III	MUCE COUN	19 Miles
Name of Pho	tographer	DAVE E	NEHL
Date	15		
Location of	Negative	SHA	
Description	NURTH	ELEVATION	LOUKING
	SOUTH	EAST	
	-	N III would	1,400,01,

Number Hof 34



Inventory#	BA 2693	3	-
B0202 - GN	HNUBRO	OR AVE OVER	ATRIBNTARY
County/State	BALTIN	MURE COUNT	IIMO
Name of Pho	tographer	DAVE DE	HL
Date	95		
Location of l	Negative _	SHA	
Description	SOUTH	ELEVATION	LODKING
3	24	1197-56ZE	Filmograph residence
Number 20	of of		



Inventory # BA 2693 BOTOZ- GWYNN BROOK AVEOVER ATRIBUTAR Name DF GWYNNS FALLS
Name OF GWYNNS FALLS
County/State BALTIMURE COUNTY/MD
Name of Photographer DAVE DIEHL
Date1 95
Location of Negative SHA
Description EAST APPROACH LOOKING WEST
Number 2 tof 3 + 4